

Inspection Photos

05/16/2017

Operator: Monsanto Oil Co #459500

Location ID: 400899

Inspection Doc. Number: 682502013

Washington County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: Monsanto Oil Co #459500
Location ID: 400899



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: Monsanto Oil Co #459500
Location ID: 400899



Photo 2: Photo taken on the location, facing north. Photo shows vegetation over the reclamation area.



Photo 3: Photo taken on the location, facing east. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: Monsanto Oil Co #459500
Location ID: 400899



Photo 4: Photo taken on the location, facing south. Photo shows vegetation over the reclamation area.



Photo 5: Photo taken on the location, facing west. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: Monsanto Oil Co #459500
Location ID: 400899



Photo 6: Photo taken to the north end of the location. Photo shows utilities that belong to the Flessner 1-A (121-09201) well directly to the east.