

Inspection Photos

05/16/2017

Operator: Magpie Operating, Inc #52530

Location ID: 316986

Inspection Doc. Number: 682502029

Washington County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: Magpie Operating, Inc #52530
Location ID: 316986



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: Magpie Operating, Inc #52530
Location ID: 316986



Photo 2: Photo taken from the location, facing east. Photo shows vegetation over the reclamation area. Photo shows utility pole remaining on location.



Photo 3: Photo taken from the location. Photo shows large areas of the location that remains bare and exposed soil. These areas are not progressing towards reclamation standards. Vegetation beginning to grow in photo appears to be undesirable weedy plant species such as kochia. 6 foot measuring stick for reference.

Inspection Photos
Operator: Magpie Operating, Inc #52530
Location ID: 316986



Photo 4: Photo taken from the location. Photo shows sign and utility pole still remaining.



Photo 5: Photo taken from the location. Photo shows sign and debris still remaining.