

Inspection Photos

05/16/2017

Operator: Magpie Operating, Inc #52530

Location ID: 316981

Inspection Doc. Number: 682502031

Washington County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: Magpie Operating, Inc #52530
Location ID: 316981



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: Magpie Operating, Inc #52530
Location ID: 316981



Photo 2: Photo taken from the location, facing east. Photo shows vegetation over the reclamation area. Photo shows utility pole(s) remaining on location.



Photo 3: Photo taken from the location. Photo shows large areas of the location that remains bare and exposed soil. These areas are not progressing towards reclamation standards.

Inspection Photos
Operator: Magpie Operating, Inc #52530
Location ID: 316981



Photo 4: Photo taken from the location. Photo shows gravel still remaining on location.



Photo 5: Photo taken from the access road, east of the location facing west. Photo shows access road has not been adequately re-contoured, re-graded and reclaimed.

Inspection Photos
Operator: Magpie Operating, Inc #52530
Location ID: 316981



Photo 6: Photo taken from the access road, east of the location facing northwest. Photo shows access road has not been adequately re-contoured, re-graded and reclaimed.



Photo 7: Photo taken from the access road, east of the location facing southwest. Photo shows access road has not been adequately re-contoured, re-graded and reclaimed.