

Inspection Photos

05/16/2017

Operator: Magpie Operating, Inc #52530

Location ID: 400749

Inspection Doc. Number: 682502033

Washington County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: Magpie Operating, Inc #52530
Location ID: 400749



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: Magpie Operating, Inc #52530
Location ID: 400749



Photo 2: Photo taken from the location. Photo shows pipe remaining in ground.



Photo 3: Photo taken from the location, facing north. Photo shows debris/equipment still remaining on the location.

Inspection Photos
Operator: Magpie Operating, Inc #52530
Location ID: 400749



Photo 4: Photo taken from the location. Photo shows debris/equipment still remaining on the location.



Photo 5: Photo taken from the location. Photo shows debris/equipment still remaining on the location.

Inspection Photos
Operator: Magpie Operating, Inc #52530
Location ID: 400749



Photo 6: Photo taken from the location. Photo shows vegetation predominantly undesirable weedy plant species such as cheat grass. This species does not contribute to the 80% desirable perennial vegetative cover per reclamation requirements.



Photo 7: Photo taken from the north east end of the location. Photo shows one of the four anchors that still remain on the location.

Inspection Photos
Operator: Magpie Operating, Inc #52530
Location ID: 400749



Photo 8: Photo taken down hill from the north end of the location. Photo shows debris/equipment still remaining.