



Photo 1: View of the project area from the northeastern corner facing center.



Photo 2: View of the northern portion of the project area from the northeastern corner facing eastward. Revegetation is largely comprised of grasses such as western wheatgrass (*Pascopyrum smithii*) and smooth brome (*Bromus inermis*),



Photo 3: View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4: View of erosional channel in the southeastern portion of the project area.



Photo 5: Another view of erosion in the southeastern portion of the project area that needs stabilization.



Photo 6: View of Canada thistles (*Cirsium arvense*) in the eastern portion of the project area.