

Inspection Photos

Location Number: 318760



Risers at wellhead not marked or capped.

Unused equipment at wellhead.



Inspection Photos

Location Number: 318760



Risers on south side of battery. Not capped or marked. GPS 40.21278, -104.74992



**Riser between tank battery and separators
Not marked or capped, GPS 40.21337, -104.74999**



Inspection Photos

Location Number: 318760



Riser inside separator berm
SE corner of berm GPS 40.21352, -104.74984



Riser inside separator berm
SE corner of berm GPS 40.21352, -104.74984

Inspection Photos

Location Number: 318760



Riser inside separator berm
SE corner of berm GPS 40.21352, -104.74984



Riser inside separator berm
SE corner of berm GPS 40.21352, -104.74984

Inspection Photos

Location Number: 318760



Riser inside separator berm
SE corner of berm GPS 40.21352, -104.74984



Riser inside separator berm
SE corner of berm GPS 40.21352, -104.74984

Inspection Photos

Location Number: 318760



Riser inside separator berm
SE corner of berm GPS 40.21352, -104.74984



Riser inside separator berm
SE corner of berm GPS 40.21352, -104.74984

Inspection Photos

Location Number: 318760



Riser inside separator berm

SE corner of berm GPS 40.21352, -104.74984



Inspection Photos

Location Number: 318760

