

Location			
Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by fence at unit		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease signs mounted to meter sheds		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Metal panels around meter sheds, VGS and pig station		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	
Equipment:			
Type: Pig Station	# 1		corrective date
Comment:	Pig launching station on east side of meter sheds		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Churchill unit		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	Shared meter run for KNODEL 21-17, 22-17, 23-17, 31-17 350' south of wellhead		
Corrective Action:		Date:	

Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electric panel and telemetry equipment at meter sheds		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Vertical Separator	# 4		
Comment:	4-Vertical gas separators 50% buried by meter sheds		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 288655 Type: WELL API Number: 125-10594 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(KNODEL 21-17, 22-17, 23-17, 31-17\) 350' S @ 39.71106/-102.09401](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Erosion on access needs maintenance. Maintain check dams on access

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT