



**photo 1:** Facing southwest along the access road toward the location.



**photo 2:** Facing south at the location.





**photo 3:** South side of the location facing north.



**photo 4:** After the cable was removed.





**photo 5:** A wood pallet remains at the north side of the location.



**photo 6:** Facing toward the surrounding pasture.