

Inspection Photos

05/22/2017

Operator: Smith Oil Properties #79905

Location ID: 406291

Inspection Doc. Number: 682502037

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: Smith Oil Properties #79905
Location ID: 406291



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: Smith Oil Properties #79905
Location ID: 406291



Photo 2: Photo taken from the location. Photo shows various pipe debris still remaining on the location.



Photo 3: Photo taken from the location. Photo shows various pipe debris still remaining on the location.

Inspection Photos
Operator: Smith Oil Properties #79905
Location ID: 406291



Photo 4: Photo of sign at the tank battery facility, north of the well location.



Photo 5: Photo taken from the battery facility, facing north. Photo shows 6 pipe risers.

Inspection Photos
Operator: Smith Oil Properties #79905
Location ID: 406291



Photo 6: 2016 Aerial imagery showing location of well and battery facility.