

# Inspection Photos

05/22/2017

Operator: Klein 21-8 Tank Battery


Weld County, CO

Aaron Trujillo  
Reclamation Specialist  
COGCC





**Photo 1:** Aerial imagery showing all wells within T2N62W Section 8. Yellow star indicates location of the Klein 21-8 tank battery



**Photo 2:** 2016 Aerial imagery of the tank battery location (outlined in yellow). Location is ~ 1 acre in size.



**Photo 3:** 2016 Aerial image. Photo shows location of all pipe risers inspector was able to locate remaining on the northern half of the location .



**Photo 4:** Photo taken from the northwest end of the location, facing east. Photo shows active tank on location. Sign says HRM, BCC currently operates location. Multiple operators appear to historically have had multiple wells associated with this battery



**Photo 5:** Photo of “~4 inch riser @ground” / “~4 inch riser”



**Photo 6:** Photo of “~3 inch x2, yellow”



**Photo 7:** Photo of “~2 inch x2, ~1 inch x1”



**Photo 8:** Photo of “~3 inch x2, connected at top”



**Photo 9:** Photo of “~3 inches laying on ground”



**Photo 10:** Photo of “~2 inch, tall”.




**Photo 11:** Photo of “~4 inches, white”



**Photo 12:** Photo of “~4 inches, white”.



**Photo 13:** Photo of “~2 inches x2, w/ ~½ inch with wires”.



**Photo 14:** 2016 Aerial image. Photo shows location of all pipe risers inspector was able to locate remaining on the southern half of the location .



**Photo 15:** Photo of “yellow ~2 inch riser”.



**Photo 16:** Photo 1/3 of “~4 inch x7”. This photo was taken on the north end of the risers, facing south.



**Photo 17:** Photo 2/3 of “~4 inch x7”. This photo was taken on the south end of the risers, facing north.



**Photo 18:** Photo 3/3 of “~4 inch x7”.



**Photo 19:** Photo of “~1 inch x6, ~4 inch x~6”



**Photo 20:** Photo of “~1 inch x6, ~4 inch x~6”



**Photo 21:** Photo of “~1 inch x6, 4 inch x~6”



**Photo 22:** Photo of “~4 inch multi line w/ ~4 inch risers x2”



**Photo 23:** Photo of “~4 inch multi line w/ ~4 inch risers x2”



**Photo 24:** Photo of “~4 inch multi line w/ ~4 inch risers x2”



**Photo 25:** Aerial image. Photo shows location of a riser found near road, to the northeast of the location.



**Photo 26:** Photo shows riser found near road, to the northeast of the location.