

Photo#1:
Overview of Location from Entry to SW .



May 19, 2017


Photo#2:

View to North over Wellhead Location.



Photo#3:

View to South over Wellhead Location.



May 19, 2017

Photo#4:

Equipment has not been removed from Location



Photo#5:



May 19, 2017

Photo#6:

Anchors & Culverts on Location.

Photo#7:



May 19, 2017

Photo#8:

Thistle plants emerging in Pad area.



Photo#9:

Houndstongue plants emerging in Pad area.



May 19, 2017

Photo#10:
White Top in Pad Area



Photo#11:
Mullein in Pad rea



May 19, 2017

Photo#12:
Unused Equipment, Debris , Pipe Risers on Location.



May 19, 2017