

# Inspection Photos

Location Number: 328313



**Photo 1 Wellhead from north**



**Photo 2 Tank Battery from east**

# Inspection Photos



**Photo 3 Separator from south**



**Photo 4 Emission Burner from south**

# Inspection Photos

**Photo 5**

**Photo 6**

