

# Inspection Photos

05/22/2017

Operator: PDC ENERGY INC - 69175

Location ID: 319218

Inspection Doc. Number: 682502069

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: PDC ENERGY INC - 69175  
Location ID: 319218



**Photo 1:** Photo of GPS verifying location.

Inspection Photos  
Operator: PDC ENERGY INC - 69175  
Location ID: 319218




**Photo 2:** Photo taken from the south end of the location, facing northeast. Photo shows overview of the location.



**Photo 3:** Photo taken from the south end of the location, facing northwest. Photo shows overview of the location.

Inspection Photos  
Operator: PDC ENERGY INC - 69175  
Location ID: 319218



**Photo 4:** Photo taken from the location. Photo shows unlabeled gas can left on location. Gas can is a (close to) full 5 gallon containing chemicals This needs to be placed into a secondary containment or removed.



**Photo 5:** Photo taken from the location. Photo shows unlabeled barrel left on location. This needs to be labeled and placed into a secondary containment or removed. Photo also shows various materials left on location. Materials appear to be plastic pipe and “hole abandonment material”.

Inspection Photos  
Operator: PDC ENERGY INC - 69175  
Location ID: 319218



**Photo 6:** Photo taken from the location, facing south. Photo show surface owner appears to have made efforts to plant crop on areas of the location without success. Remediation efforts appear to be in process as indicated under remediation project #8954.




**Photo 7:** Photo taken from the location, facing south. Photo show surface owner appears to have made efforts to plant crop on areas of the location without success. Remediation efforts appear to be in process as indicated under remediation project #8954.

Inspection Photos  
Operator: PDC ENERGY INC - 69175  
Location ID: 319218



**Photo 8:** Photo of GPS verifying location.

Inspection Photos  
Operator: PDC ENERGY INC - 69175  
Location ID: 319218



**Photo 9:** 2016 aerial imagery. Photo shows disturbance of the location (not including access road) is ~6 acres in size without site stabilization and erosion controls.