



**Photo 1: View of unused equipment and tank located approximately 665 feet south of the PA'd well.**



**Photo 2: View of oily material at a connection point for the tank in Photo 1.**



**Photo 3: View of the well pad area from the northwestern corner facing center.**



**Photo 4: View of the northern portion of the project area from the northwestern corner facing eastward. Vegetation in the foreground is the noxious weed-Russian knapweed.**