

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2017

Submitted Date:

05/22/2017

Document Number:

685303095**FIELD INSPECTION FORM**Loc ID 325561 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215005	WELL	PR	11/29/1983	GW	067-06610	HOTT 30-01 1	PR

General Comment:[See link at end of report for path to downloadable pictures.](#)

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Old sign left on location.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Corrective action completed.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	215005	Type:	WELL	API Number:	067-06610	Status:	PR	Insp. Status:	PR

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Metal containment ring around produce water tank.
Waddles	Pass					
Gravel	Pass					
Ditches	Pass	Gravel	Pass			
Rip Rap	Pass					
Compaction	Pass	Ditches	Pass			
Sediment Traps	Pass					

Comment: [Corrective action completed.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401289044	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4152502
685303125	Wellhead sign with old sign in background.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4152460
685303126	Produced water tank with visible label.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4152461
685303127	New location berm along backside of location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4152462
685303128	Rip rap installed to repair and control erosion.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4152463
685303129	Down slope view of rip rap and sediment traps.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4152464
685303130	Location overview.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4152465