

# Inspection Photos

05/30/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 329000

Inspection Doc. Number: 682502076

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 329000



**Photo 1:** Photo taken from the well location facing north. Photo shows vegetation over the reclamation area.



**Photo 2:** Photo taken from the well location facing south. Photo shows vegetation over the reclamation area.

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 329000



**Photo 3:** Photo taken from the southwest end of the tank battery location. Inspection Doc. # 682401035 documented facilities remaining at battery location. All pipe and production facilities have been removed, however, battery location has not been reclaimed.



**Photo 4:** Photo taken from the southeast corner of the tank battery location. Photo shows tank battery location has not been reclaimed. Adjacent reference areas appear to be cropland that have recently been tilled.