



Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	ok		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	ROD IRON FENCE		
Corrective Action:			Date:
<b>Equipment:</b>			
Type:	Plunger Lift	# 1	corrective date
Comment:	INTERMITTER CONTROLLER ON WELLHEAD		
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type	Ignitor/Combustor		
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 266420 Type: WELL API Number: 123-21366 Status: SI Insp. Status: PR

**Producing Well**

Comment: pr

Corrective Action:

Date:

**BradenHead**

Comment: Breadenhead plumbed to surface

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002c. PROTECTION OF SOILS Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass  
1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass  
Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685502850	BATTERY EQUIPMENT AND WELLHEAD	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4158538">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4158538</a>