

Photo#1:  
View North over Location Center



Photo#2:  
View South over Location Center



May 27,2017

Photo#3:  
View East over Location Center



Photo#4:  
View West over Location Center



May 27, 2017

Photo#5:

A few Bare areas remain with emerging Thistle & Curly Dock.



May 27, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Tom Brown ZAHM PA API#077-08543