

Inspection Photos

05/31/2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP
- 47120

Location ID: 327317

Inspection Doc. Number: 682502088
Weld County, CO

Aaron Trujillo
Reclamation Specialist
COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE
LP - 47120
Location ID: 327317



Photo 1: Photo taken from the west end of the location, facing east. Photo shows riser equipment remains on location. Photo also shows gravel on location and that location remains predominantly unvegetated.



Photo 2: Photo taken from the southeast end of the location, facing northwest. Photo shows location remains graveled and unvegetated.

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE
LP - 47120
Location ID: 327317



Photo 3: Photo taken from the southeast end of the location, facing west. Photo shows location remains graveled and unvegetated. .



Photo 4: Photo taken from the northwest end of the location. Photo shows musk thistle.

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE
LP - 47120
Location ID: 327317



Photo 5: Photo taken from the northwest end of the location, facing west. Photo shows access road remains unreclaimed.



Photo 6: Photo taken from the access road entrance. Photo shows access road remains unreclaimed; gate and cattle guard remains.