

Inspection Photos
Location Name: Frank 32-24
API: 05-123-18646



Photo 1: Pressure test



Photo 2: Risers at wellhead

Inspection Photos
Location Name: Frank 32-24
API: 05-123-18646



Photo 3: Risers at separator



Photo 4: Risers in separator

Inspection Photos
Location Name: Frank 32-24
API: 05-123-18646



Photo 5: Risers at tank battery