

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2017

Submitted Date:

05/31/2017

Document Number:

675103647**FIELD INSPECTION FORM**

Loc ID 334152 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Encana		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279202	WELL	PR	08/01/2013	GW	045-11014	KEINATH 4-2 (OB4)	EG
279203	WELL	PR	04/01/2014	GW	045-11013	KEINATH 33-15 (OB4)	EG
283570	WELL	PR	01/01/2012	GW	045-11941	KEINATH 4-3 (OB4)	EG

**General Comment:**2017 Flowline NTO inspection 1000' buffer

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	IN USE; 3-3" steel risers from wells to separators. 3-3" steel risers from gas out separator to sales line. 3-2" steel risers from separator water/oil dump to tank battery. 1 -2" steel riser from separator gas out to gas meter sales. 2-3" steel risers from separator water/oil dump to tank battery.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	39.38472/-108.11164		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:	39.38472/-108.11164		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		

Comment:	Chem tote with secondary containment			
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	39.38472/-108.11164			
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	STEEL AST		39.384920,-108.111720	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 279202 Type: WELL API Number: 045-11014 Status: PR Insp. Status: EG

**Producing Well**

Comment: PR no leaks/venting, bradenhead/well remote pressure monitoring present

Corrective Action:

Date:

**Flowline**

#1 Type: Well Site

of Lines

**Flowline Description**

Flowline Type: Well Site

Size:

Material:

Variance:

Age:

Contents:

**Integrity Summary**

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

**Pressure Testing**

Witnessed:

Test Result:

Charted:

**COGCC Rules(check all that apply)**

☐ 1101. Installation and Reclamation

☒ 1102. Operations, Maintenance, and Repair

☐ 1103. Abandonment

Comment: IN USE; 3-3" steel risers from wells to separators. 3-3" steel risers from gas out separator to sales line. 3-2" steel risers from separator water/oil dump to tank battery. 1-2" steel riser from separator gas out to gas meter sales. 2-3" steel risers from separator water/oil dump to tank battery.

Corrective Action:

Date:

Facility ID: 279203 Type: WELL API Number: 045-11013 Status: PR Insp. Status: EG

**Producing Well**

Comment: PR no leaks/venting, bradenhead/well remote pressure monitoring present

Corrective Action:

Date:

Facility ID: 283570 Type: WELL API Number: 045-11941 Status: PR Insp. Status: EG

**Producing Well**

Comment: PR no leaks/venting, bradenhead/well remote pressure monitoring present

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Gravel	Pass			
		Ditches	Pass			
Compaction	Pass					

Comment: [No sediment flow evident](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675103648	Flowline photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4159730">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4159730</a>