

Exxon GM 24-1
Api: 05-045-07259
Inspection # 674703977



Location from entrance.

Exxon GM 24-1
Api: 05-045-07259
Inspection # 674703977



Well heads



Well head

Exxon GM 24-1
Api: 05-045-07259
Inspection # 674703977



Unused riser painted orange at well head GM 24-1

Exxon GM 24-1
Api: 05-045-07259
Inspection # 674703977



Separators

Unused risers painted orange at separators

Exxon GM 24-1
Api: 05-045-07259
Inspection # 674703977



Tank Battery with a n used 2" riser painted orange.