

Inspection Photos  
Location Name: Hornung Sec 28 4N 68W



11-28 wellhead looking south



11-28 wellhead looking north valve seep



**Inspection Photos**  
**Location Name: Hornung Sec 28 4N 68W**



**21-28 and 52-28 wellheads looking southeast. No sign for 21-28**



**52-28 wellhead looking south**



Inspection Photos  
Location Name: Hornung Sec 28 4N 68W



21-28 wellhead looking south



Tank battery sign on south side of battery

**Inspection Photos**  
**Location Name: Hornung Sec 28 4N 68W**



**Production tanks looking northwest**



**Production tanks looking south**

**Inspection Photos**  
**Location Name: Hornung Sec 28 4N 68W**



**North side of production tanks looking east**



**North side of separators looking south**

**Inspection Photos**  
**Location Name: Hornung Sec 28 4N 68W**



**Separators looking south**



**Separators looking southwest**

**Inspection Photos**  
**Location Name: Hornung Sec 28 4N 68W**



**Risers at ECD. Looking southeast**

