



photo 1: Facing north toward the location.



photo 2: There are Noxious weeds (Canada, Musk, thistle) growing along the access road and at the location.



photo 3: There is an electric utility and pipe riser that remain at the west side of the location.



photo 4: An unknown pipe riser remains at the location. Lat/Long:39.78410,-104.36549.