

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2017

Submitted Date:

05/26/2017

Document Number:

674703957**FIELD INSPECTION FORM**
 Loc ID 334825 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**28 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2760	COGCCInspectionReports@terraep.com	
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210977	WELL	PR	09/05/1998	GW	045-06735	BATTLEMENT MESA PARTNERS GV 82-5	PR
211185	WELL	PR	12/21/1995	GW	045-06944	CURFMAN W 15-5	PR
293561	WELL	PR	07/27/2008	GW	045-15041	BATTLEMENT MESA PARTNERS PA 433-5	PR
293563	WELL	PR	11/19/2007	GW	045-15042	BATTLEMENT MESA PARTNERS PA 434-5	PR
293564	WELL	PR	07/27/2008	GW	045-15043	BATTLEMENT MESA PARTNERS PA 424-5	PR
293565	WELL	PR	07/27/2008	GW	045-15044	BATTLEMENT MESA PARTNERS PA 24-5	PR
301575	WELL	PR	02/28/2010	GW	045-18184	BATTLEMENT MESA PA 423-5	PR
301576	WELL	PR	12/18/2009	GW	045-18185	BATTLEMENT MESA PA 524-5	PR
301577	WELL	PR	01/31/2010	GW	045-18186	BATTLEMENT MESA PA 333-5	PR
301578	WELL	PR	02/17/2009	GW	045-18187	BATTLEMENT MESA PA 13-5	PR
301579	WELL	PR	04/16/2011	GW	045-18188	BATTLEMENT MESA PA 324-5	PR
301580	WELL	PR	04/16/2011	GW	045-18189	BATTLEMENT MESA PA 323-5	PR
301581	WELL	PR	04/16/2011	GW	045-18190	BATTLEMENT MESA PA 314-5	PR
301582	WELL	PR	04/16/2011	GW	045-18191	BATTLEMENT MESA PA 23-5	PR
301583	WELL	PR	04/16/2011	GW	045-18192	BATTLEMENT MESA PA 313-5	PR

301584	WELL	PR	01/31/2010	GW	045-18193	BATTLEMENT MESA PA 14-5	PR
301585	WELL	PR	02/28/2010	GW	045-18194	BATTLEMENT MESA PA 514-5	PR
301586	WELL	PR	04/16/2011	GW	045-18195	BATTLEMENT MESA PA 34-5	PR
301587	WELL	PR	04/16/2011	GW	045-18196	BATTLEMENT MESA PA 414-5	PR
301588	WELL	PR	01/31/2010	GW	045-18197	BATTLEMENT MESA PA 413-5	PR
301589	WELL	PR	04/16/2011	GW	045-18198	BATTLEMENT MESA PA 334-5	PR
301590	WELL	PR	04/16/2011	GW	045-18199	BATTLEMENT MESA PA 33-5	PR

**General Comment:**

2017 Flowline NTO Inspection 1000' Buffer

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR				
Comment:					
Corrective Action:				Date:	

<b>Equipment:</b>					corrective date
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 20				
Comment:	Center of spread 39.46436 -108.02051				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 2				
Comment:					
Corrective Action:				Date:	
Type: Flow Line	#				
Comment:	In use: 22 - 2" risers at wells 2 - 2" risers at tanks 58- 2" risers at separators 1 - 8" at separators 1 - 4" riser at south end of tank battery and edge of location.				
Corrective Action:				Date:	
Type: Bird Protectors	# 12				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 20				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 3				
Comment:					
Corrective Action:				Date:	
Type: Flow Line	# 1				
Comment:	Unused: 1 - 1" gas supply line for removed combuster. 39.46426 -108.02043 to 39.46412 -108.02023 Terra plans to remove unsued line from location.				
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	500 gallons
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:



Inspected Facilities									
Facility ID:	210977	Type:	WELL	API Number:	045-06735	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	211185	Type:	WELL	API Number:	045-06944	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	293561	Type:	WELL	API Number:	045-15041	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	293563	Type:	WELL	API Number:	045-15042	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	293564	Type:	WELL	API Number:	045-15043	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	293565	Type:	WELL	API Number:	045-15044	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	301575	Type:	WELL	API Number:	045-18184	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	301576	Type:	WELL	API Number:	045-18185	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: 301577	Type: WELL	API Number: 045-18186	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 301578	Type: WELL	API Number: 045-18187	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 301579	Type: WELL	API Number: 045-18188	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 301580	Type: WELL	API Number: 045-18189	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 301581	Type: WELL	API Number: 045-18190	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 301582	Type: WELL	API Number: 045-18191	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 301583	Type: WELL	API Number: 045-18192	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 301584	Type: WELL	API Number: 045-18193	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:



Facility ID: 301585	Type: WELL	API Number: 045-18194	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 301586	Type: WELL	API Number: 045-18195	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 301587	Type: WELL	API Number: 045-18196	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 301588	Type: WELL	API Number: 045-18197	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 301589	Type: WELL	API Number: 045-18198	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 301590	Type: WELL	API Number: 045-18199	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401294305	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4157064">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4157064</a>
674703963	GV 82-5 location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4157050">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4157050</a>