



photo 1: Facing east at the location.



photo 2: Facing north at the location. There is a pit with cement and pipe debris that remains.



photo 3: Facing west at the location.



photo 4: The south toward the surrounding crop field.