



photo 1: Facing southwest toward the tank battery site.



photo 2: There is weeds and vegetation growing inside the berm and around the equipment.



photo 3: There are noxious weeds (Diffuse knapweed) throughout the location.



photo 4: Facing west at the north side of the tank battery site.



photo 5: A pipe riser was found near the tank battery at Lat/Long:39.60924,-104.32427.



photo 6: There is wire and trash debris along the fence that needs to be removed.