



*Photos 1 & 2 - Close-up on wellhead sign with COGCC info (top) and photo of wellhead with polished rod (bottom).*







*Photo 3 - Close-up on wellhead. Note: COGCC warning tags, localized oil-stained soil, and minor excavation at base of wellhead.*





*Photo 4 - Electrical control boxes west of wellhead.*





*Photos 5 & 6 - Abandoned flowline risers at former TTOC battery location have been tagged and painted by COGCC, per 2017 Flowline NTO.*



*Photo 7 - Former TTOC Battery location. Note: Ward Petroleum Corporation logo has replaced TTOC information on horizontal separator in background.*