


Photo#1:
View North over Location Center



Photo#2:
View South over Location Center



May 30, 2017

Photo#3:
View East over Location Center



May 30, 2017

Photo#4:
View West over Location Center




Photo#5:

Open Cellar housing PA Marker posing safety hazard to Public & endangerment to Wildlife.

Photo#6:

Dead Wildlife floating in Cellar.



May 30, 2017

Photo#7:

Debris & equipment remains on site.



Photo#8:



May 30, 2017

Photo#9:

Thistle growing on Soil piles.

Photo#10:



May 30, 2017

Photo#11:

Guy Anchor, Drilling Cable & Safety Hazard Indicated by arrow



Photo#12:



May 30, 2017