

Lila Cummins A2, A3, and A 4 Inspection Closure 5-26-17





LILA CUMMINS A 2
BP AMERICA PRODUCTION COMPANY
API #: 05-007-08018 DWR #: 70102-F
LEASE #: N/A CA #: N/A
SURFACE LOCATION:
SWNE SEC 4 - T33N - R8W
1320' FNL 1995' FEL
BOTTOM HOLE LOCATION:
SAME AS SURFACE LOCATION
LATITUDE: 37.13659236
LONGITUDE: -107.7206719
NEAREST ADDRESS: 3951 CR 311
BP CONTROL CENTER 24 HR. PHONE #: 970-247-6916
EMERGENCY CONTACT #: 911

LILA CUMMINS A 3
BP AMERICA PRODUCTION COMPANY
API #: 05-067-09602 DWR #: 70215-F
LEASE #: N/A CA #: N/A
SURFACE LOCATION:
NWNE SEC 4 - T33N - R8W
1217' FNL 1992' FEL
BOTTOM HOLE LOCATION:
NWNE SEC 4 - T33N - R8W
1800' FNL 2330' FNL
LATITUDE: 37.13688374
LONGITUDE: -107.7206582
NEAREST ADDRESS: 3951 CR 311
BP CONTROL CENTER 24 HR. PHONE #: 970-247-6916
EMERGENCY CONTACT #: 911

LILA CUMMINS A 4
BP AMERICA PRODUCTION COMPANY
API #: 05-057-09617 DWR #: 70218-F
LEASE #: N/A CA #: N/A
SURFACE LOCATION: NWNE SEC 4 - T33N - R8W 1227' FNL 1962' FEL
BOTTOM HOLE LOCATION: NWNE SEC 4 - T33N - R8W 1789' FNL 406' FEL
LATITUDE: 37.1368776 LONGITUDE: -107.7205176
NEAREST ADDRESS: 3951 CR 311
BP CONTROL CENTER 24 HR. PHONE #: 970-247-6916
EMERGENCY CONTACT #: 911



