



**Photo 1:** View of the project area from the northeastern corner facing center.



**Photo 2:** View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is largely comprised of grasses such as western wheatgrass (*Pascopyrum smithii*) and smooth brome (*Bromus inermis*).



**Photo 3: View of area along the eastern edge of the working area where concentrated stormwater flows off of the well pad and is eroding the interim reclamation area.**



**Photo 4: View of headcut approximately 2 feet wide and up to 4 feet deep in the southeastern portion of the project area.**



**Photo 5: View of erosional channel forming within the southern portion of the project area.**



**Photo 6: View of liner material in the eastern portion of the project area.**



**Photo 7: View of musk thistles (*Carduus nutans*) in the eastern portion of the project area.**