



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner facing southward. Revegetation is sparse on cut-slopes and largely comprised of grasses such as western wheatgrass (*Pascopyrum smithii*) and Indian ricegrass (*Achnatherum hymenoides*).



Photo 3: View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 4: View of area along the southeastern edge of the well pad where concentrated stormwater flows off of the working area and is starting to cause erosion.