

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/01/2017

Submitted Date:

06/05/2017

Document Number:

680301981

**FIELD INSPECTION FORM**

Loc ID 313907 Inspector Name: SCHURE, KYM On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 53790  
Name of Operator: MARKUS PRODUCTION, INC  
Address: 39 FAIRWAY LANE  
City: LITTLETON State: CO Zip: 80123

**Findings:**

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Brown, Mark	(720) 350-8858	mark@markusproduction.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
227089	WELL	PR	03/26/2014	OW	087-07832	WELKER 43-30	PA

**General Comment:**

**P&A COMPLETE & SATISFACTORY** [Begin reclamation process](#)

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	P&A Satisfactory Begin reclamation process		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Satisfactory		Date: _____
Corrective Action:			
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Other	# 0		corrective date
Comment:	Remove all equipment. Begin reclamation process until final reclamation is approved from COGCC		
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 227089 Type: WELL API Number: 087-07832 Status: PR Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: Bohler Well Service

Contractor Phone: 970-522-3078

Surface Casing

Cement Volume (sx): 140+10

Circulate to Surface: YES

Cement Fall Back:           

Top Job, 1" Volume: YES

Intermediate Casing

Cement Volume (sxs):                   

Good Return During Job:           

Production Casing

Cement Volume (sx): 5+25+50

Good Return During Job: YES

Plugging Operations

Depth Plugs(feet range): 6348,5500,1380,258

Cement Volume (sx): 5+25+50+140+10

Good Return During Job: YES

Cement Type: G

Comment: P&A COMPLETE SATISFACTORY Well pipe has been cut off @ (7') below grade, welded cap w/logistics/info., backfilled and smoothed out surface. NO problems indicated.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: [Continue stormwater erosion management BMP's until final reclamation is approved from COGCC](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">P&amp;A COMPLETED SATISFACTORY - Begin reclamation process, notify COGCC Reclamation Group and COGCC Environmental Group for directives and approvals.</a>	schureky	06/05/2017