
Schlumberger
Platform Express
Three-Detector Lithology Density
Compensated Neutron
Array Induction Imager Tool
Gamma Ray
Caliper
Bit Size
Mud Type
Density
Viscosity
Fluid Loss
Resistivity
Source
Rm @ BHT
Rmf @ BHT
Rmc @ BHT
Mud Cake
Rm @ MRT
Time Since Circulation
Max Recorded Temperature
Equipment Number
Location
Recorded By
Witnessed By
Run Number
Depth Driller
Depth Logger
Bottom Logged Interval
Top Logged Interval
Casing Driller
Casing Logger
Bit Size
Type Fluid in Hole
Density
Viscosity
PH
Fluid Loss
Source of Sample
Rm @ Measured Temp
Rmf @ Measured Temp
Rmc @ Measured Temp
Source of Rmf and Rmc
Rm @ BH

S4	0.000	0.000	0.000
S5	0.000	0.000	0.000
S6	0.000	0.000	0.000
S7	0.000	0.000	0.000
S8	0.000	0.000	0.000

Cutters® Wireline Service, Inc.
A Cased Hole Wireline Company

Company	CHEVRON
Well	CARNEY #4-34
Field	RANGLEY
County	RIO BLANCO
State	COLORADO