

Inspection Photos

Location Name: LAMB 15 C

API: 05 -123-34896



1" SUPPLY GAS LINE LINE



**VRU DISCHARGE LINE TESTED GOOD
PRESSURE 111 PSI**

