



photo 1: Facing east toward the former access road.



photo 2: There are noxious weeds (Canada and Musk thistle) growing along the access road.



photo 3: Facing east toward the location.




photo 4: There is predominately undesirable weed growth (*Kochia* sp.) at the location.