

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/25/2017

Submitted Date:

06/01/2017

Document Number:

674703962**FIELD INSPECTION FORM**

Loc ID 335106	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				Findings: <u>28</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2760	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285878	WELL	PR	04/27/2007	GW	045-12579	NAUGLE RWF 311-30	PR
285879	WELL	PR	01/29/2007	GW	045-12578	NAUGLE PA 342-25	PR
285880	WELL	PR	06/30/2008	GW	045-12577	NAUGLE PA 341-25	PR
285881	WELL	PR	04/27/2007	GW	045-12576	NAUGLE RWF 412-30	PR
287048	WELL	PR	06/12/2007	GW	045-12846	NAUGLE PA 41-25	PR
287049	WELL	PR	06/12/2007	GW	045-12845	NAUGLE PA 441-25	PR
287050	WELL	PR	06/12/2007	GW	045-12844	NAUGLE PA 541-25	PR
287051	WELL	PR	05/31/2008	GW	045-12843	NAUGLE PA 42-25	PR
287052	WELL	PR	06/12/2007	GW	045-12842	NAUGLE RWF 411-30	PR
287053	WELL	PR	06/30/2008	GW	045-12841	NAUGLE RWF 11-30	PR
287054	WELL	PR	06/12/2007	GW	045-12840	NAUGLE RWF 12-30	PR
287055	WELL	PR	06/12/2007	GW	045-12839	NAUGLE RWF 312-30	PR
287056	WELL	PR	06/30/2008	GW	045-12838	NAUGLE RWF 21-30	PR
287057	WELL	PR	08/20/2008	GW	045-12837	NAUGLE RWF 321-30	PR
287058	WELL	PR	07/17/2007	GW	045-12836	NAUGLE RWF 22-30	PR
287059	WELL	PR	06/12/2007	GW	045-12835	NAUGLE RWF 421-30	PR
287097	WELL	PR	06/12/2007	GW	045-12887	NAUGLE RWF 422-30	PR
287098	WELL	PR	06/12/2007	GW	045-12870	NAUGLE RWF 322-30	PR
287099	WELL	PR	06/12/2007	GW	045-12869	NAUGLE RWF 512-30	PR
287100	WELL	PR	06/15/2007	GW	045-12868	NAUGLE RWF 521-30	PR
292163	WELL	PR	09/06/2007	GW	045-14613	NAUGLE PA 542-25	PR
292164	WELL	PR	09/06/2007	GW	045-14612	NAUGLE PA 442-25	PR

General Comment:



Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Type	WELLHEAD				
Comment:					
Corrective Action:				Date:	

Equipment:					corrective date
Type: Bird Protectors	# 12				
Comment:					
Corrective Action:				Date:	
Type: Flow Line	#				
Comment:	In use: 53 - 2" risers and 4 - 1" risers at separators, 22 - 2" risers at well heads 3 - 2" risers at tanks				
Corrective Action:				Date:	
Type: Plunger Lift	# 20				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 2				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 2				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 5				
Comment:	Chemical containers at wells				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 20				
Comment:	39.50198 -107.93935				
Corrective Action:				Date:	
Type: Flow Line	# 1				
Comment:	Not in use: 3" line from tanks to combustor has been take apart and plan to pick up and remove from location.				
Corrective Action:				Date:	
Type: Emission Control Device	# 1				
Comment:	No longer in service				
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	200 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)						
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	285878	Type:	WELL	API Number: 045-12579	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	285879	Type:	WELL	API Number: 045-12578	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	285880	Type:	WELL	API Number: 045-12577	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	285881	Type:	WELL	API Number: 045-12576	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	287048	Type:	WELL	API Number: 045-12846	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	287049	Type:	WELL	API Number: 045-12845	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	287050	Type:	WELL	API Number: 045-12844	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	287051	Type:	WELL	API Number: 045-12843	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:

Facility ID: 287052	Type: WELL	API Number: 045-12842	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 287053	Type: WELL	API Number: 045-12841	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 287054	Type: WELL	API Number: 045-12840	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 287055	Type: WELL	API Number: 045-12839	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 287056	Type: WELL	API Number: 045-12838	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 287057	Type: WELL	API Number: 045-12837	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 287058	Type: WELL	API Number: 045-12836	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 287059	Type: WELL	API Number: 045-12835	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 287097	Type: WELL	API Number: 045-12887	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 287098	Type: WELL	API Number: 045-12870	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 287099	Type: WELL	API Number: 045-12869	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 287100	Type: WELL	API Number: 045-12868	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 292163	Type: WELL	API Number: 045-14613	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 292164	Type: WELL	API Number: 045-14612	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401298097	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160625
674703986	PA 41-25 location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160622