

Inspection Photos
Location Name: Gillette*Lois #1
API: 05-123-22125



Photo 1: Location, looking E. No bradenhead at surface.



Photo 2: Stormwater erosion on S side of location, failure of wattle BMP.