

Inspection Photos

6/8/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 323427

Inspection Doc. Number: 682502206

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator: NOBLE ENERGY INC - 100322

Location ID: 323427



Photo 1: Photo taken from the well location. Photo shows crop establishment appears to be uniform throughout well location.



Photo 2: Photo taken from the battery location, facing south. Photo shows battery location and access road have not been reclaimed.