

Inspection Photos
Location Name: Stephens 7-14
API: 05-123-18769



Wellhead



2" steel riser and 1" process riser

Inspection Photos
Location Name: Stephens 7-15
API: 05-123-23858



Wellhead



2" steel riser and 1" process riser

Inspection Photos
Location Name: Stephens 7-14
API: 05-123-18769



2" steel riser after process riser removal



Separator burner stack

Inspection Photos
Location Name: Stephens 7-14
API: 05-123-18769



Production facility



Trash

Inspection Photos
Location Name: Stephens 7-14
API: 05-123-18769



Unused equipment



Stephens 7-15 2" steel riser after 1" process riser removal