

Inspection Photos

6/9/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 319038

Inspection Doc. Number: 682502210

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 319038



Photo 1: Photo taken from the tank battery location. Photo shows unvegetated areas at the battery that are not progressing towards COGCC 1000 series reclamation standards



Photo 2: Photo taken from the tank battery location. Photo shows riser still remaining.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 319038



Photo 3: Photo taken from the well location. Photo shows vegetation over the well area. Reclamation in process.