

Inspection Photos
Location Name: Pole Gulch Unit 2
API: 05-081-60067



Photo 1. Overview of location taken at entrance facing southeast.

Inspection Photos
Location Name: Pole Gulch Unit 2
API: 05-081-60067



Photo 2. Risers at wellhead. Unlabeled containers adjacent to wellhead.



Photo 3. Unused risers. Debris.

Inspection Photos
Location Name: Pole Gulch Unit 2
API: 05-081-60067



Photo 4. Unused risers.



Photo 5. Risers at separator.

Inspection Photos
Location Name: Pole Gulch Unit 2
API: 05-081-60067



Photo 6. Risers at separator.



Photo 7. Unlabeled tanks. Open gauge hatch. No wildlife protection on exhaust.

Inspection Photos
Location Name: Pole Gulch Unit 2
API: 05-081-60067



Photo 8. Pit with no ID at 40.99956, -107.73175



Photo 9. Landfarm area in foreground, pit in background.