

Inspection Photos
Location Name: Cherokee Ridge 14-34R
API: 05-081-07461



Photo 1. Overview of location taken at entrance facing southeast.

Inspection Photos
Location Name: Cherokee Ridge 14-34R
API: 05-081-07461



Photo 2. Risers at wellhead.



Photo 3. Separation equipment overview (1 of 3).

Inspection Photos
Location Name: Cherokee Ridge 14-34R
API: 05-081-07461



Photo 4. Separation equipment overview (2 of 3).



Photo 5. Risers in separation equipment area.

Inspection Photos
Location Name: Cherokee Ridge 14-34R
API: 05-081-07461



Photo 6. Risers in separation equipment area.



Photo 7. Risers in separation equipment area.

Inspection Photos
Location Name: Cherokee Ridge 14-34R
API: 05-081-07461



Photo 8. Risers in separation equipment area.



Photo 9. Separation equipment overview (3 of 3).

Inspection Photos
Location Name: Cherokee Ridge 14-34R
API: 05-081-07461



Photo 10. Risers at tanks.



Photo 11. Produced water leak.

Inspection Photos
Location Name: Cherokee Ridge 14-34R
API: 05-081-07461



Photo 12. Close up of spilled material with visible sheen.



Photo 13. Source of spill and ongoing drip leak.