

Inspection Photos
Location Name: Samuel J 7-9
API: 05-123-25604



Production facility



Unused 2" riser

Inspection Photos
Location Name: Samuel J 7-9
API: 05-123-25604



Unused 2" riser



Unused 2" riser

Inspection Photos
Location Name: Samuel J 7-9
API: 05-123-25604



Wellheads and 2" risers



East crude oil tank