

**Inspection Photos**  
**Location Name: Dunning 1**  
**API # 05-069-06080**



**Location from entrance looking west**



**Photo 2. North side of tank battery looking east**

**Inspection Photos**  
**Location Name: Dunning 1**  
**API # 05-069-06080**



**Photo 3. Wellhead**



**Photo 4. Manifold shed**

**Inspection Photos**  
**Location Name: Dunning 1**  
**API # 05-069-06080**



**Photo 5. Unused 2" riser in shed. 2" riser open to atmosphere**