

Inspection Photos
Location Name: Hein & Hart 1 Tank Battery
Facility ID # 451017



Photo 1. Battery entrance looking north from County road




Photo 2. Unused unmarked plugged riser in SE corner tank berm

Inspection Photos
Location Name: Hein & Hart 1 Tank Battery
Facility ID # 451017



Photo 3. Containment device full



Photo 4. Production tank looking south.

Inspection Photos
Location Name: Hein & Hart 1 Tank Battery
Facility ID # 451017



Photo 5. Battery looking south from north end of water vault. Note lack of secondary containment .



Photo 6. Water vault lid moved over. Note lack of secondary containment .

Inspection Photos
Location Name: Hein & Hart 1 Tank Battery
Facility ID # 451017



Photo 7. Looking south from water vault. 2-2" risers not marked not locked out tagged out.



Photo 8. Unused 3-3" & 1-2" risers north of separator



Inspection Photos
Location Name: Hein & Hart 1 Tank Battery
Facility ID # 451017



Photo 9. Looking east at separator.



Photo 10. Separator looking NE