

Inspection Photos
Location Name: Schrage #1 & Tank Battery
API # 123-08612 Facility ID # 451018



Photo 1. Wellhead looking SE



Photo 2. Wellhead and battery looking north

Inspection Photos
Location Name: Schrage #1 & Tank Battery
API # 123-08612 Facility ID # 451018



Photo 3. Separator, ECD. Looking north



Photo 4. ECD and heater treater. Looking north

Inspection Photos
Location Name: Schrage #1 & Tank Battery
API # 123-08612 Facility ID # 451018



Photo 5. Riser north side of shed Not marked or tagged.



Photo 6. Inside treater shed. Note stained soil.

Inspection Photos
Location Name: Schrage #1 & Tank Battery
API # 123-08612 Facility ID # 451018



Photo 7. West side of heater treater. Note 2-3" line not hooked up



Photo 8. Unused 3-3" & 1-2" risers north of separator

Inspection Photos
Location Name: Schrage #1 & Tank Battery
API # 123-08612 Facility ID # 451018



Photo 9. 3" riser in shed plugged not tagged or marked.



Photo 10. 2-2" riser between tank and separator/treater. Not marked or locked out

Inspection Photos
Location Name: Schrage #1 & Tank Battery
API # 123-08612 Facility ID # 451018



Photo 11. Looking north at production tank.



Photo 12. Spillage at loadline

Inspection Photos
Location Name: Schrage #1 & Tank Battery
API # 123-08612 Facility ID # 451018



Photo 13. loadline spillage, No wildlife protection.



Photo 14. Sign at tank conflicts with location

Inspection Photos

Location Name: Schrage #1 & Tank Battery

API # 123-08612 Facility ID # 451018



Photo 15. Looking south at eastside of production tank

