

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/08/2017

Submitted Date:

06/09/2017

Document Number:

680401652

FIELD INSPECTION FORM

Loc ID 334508 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 760 HORIZON DRIVE #101
City: GRAND JUNCTION State: CO Zip: 81506

Findings:

- 15 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|---------------------------------------|---------------------------------|
| Bankert, Wayne | 970-683-5419 | cogccnotifications@laramie-energy.com | All inspections |
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 221964 | WELL | PR | 04/04/2017 | GW | 077-08566 | MCDANIEL 11-10 | PR |
| 273822 | WELL | PR | 12/01/2014 | GW | 077-08818 | MC DANIEL 11-8 | PR |
| 273823 | WELL | PR | 06/01/2011 | GW | 077-08817 | MCDANIEL 11-9 | PR |
| 273824 | WELL | IJ | 01/28/2016 | DSPW | 077-08815 | MCDANIEL 11-16 | TA |
| 296116 | WELL | PR | 03/01/2017 | GW | 077-09652 | MCDANIEL 11-16A | PR |
| 296118 | WELL | PR | 07/01/2011 | GW | 077-09654 | MCDANIEL 11-9C | PR |
| 296119 | WELL | PR | 07/01/2011 | GW | 077-09655 | MCDANIEL 11-9B | PR |
| 296120 | WELL | PR | 06/26/2010 | GW | 077-09650 | MCDANIEL 11-10C | PR |
| 296121 | WELL | PR | 06/18/2010 | GW | 077-09649 | MCDANIEL 11-10A | PR |
| 296124 | WELL | PR | 12/13/2010 | GW | 077-09646 | MCDANIEL 11-10B | PR |
| 297881 | WELL | PR | 10/01/2012 | GW | 077-09709 | MCDANIEL 11-9A | PR |

General Comment:

[Routine UIC Inspection.](#)

Location

| | | | |
|--------------------|--------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |
| Type | Main | | |
| comment: | | | |
| Corrective Action | | | Date: |

Overall Good:

| | | | |
|----------------------|----------------------|--|-------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|----------------------------------|----------------------|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: _____ |

Overall Good:

| | | | |
|--|----------------------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: | No | | |
| Comment: | <input type="text"/> | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |

| | | | |
|--------------------|-------------------------------|--|-------|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panel fence around wellheads. | | |
| Corrective Action: | | | Date: |

| | | | | | |
|-----------------------------------|------|--|--|--|-----------------|
| Equipment: | | | | | corrective date |
| Type: Plunger Lift | # 10 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Type: Horizontal Heated Separator | # 10 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| Tanks and Berms: | | | | | | |
|-------------------------|---|----------|-----------|---------|-----------------------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 2 | 300 BBLS | STEEL AST | | 39.289417,-107.846957 | |

| | | |
|--------------------|--|-------|
| Comment: | | |
| Corrective Action: | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 2 | 400 BBLs | STEEL AST | | 39.289417,-107.846957 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | |
| | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 221964 Type: WELL API Number: 077-08566 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift
 Corrective Action: _____ Date: _____

Facility ID: 273822 Type: WELL API Number: 077-08818 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift
 Corrective Action: _____ Date: _____

Facility ID: 273823 Type: WELL API Number: 077-08817 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift
 Corrective Action: _____ Date: _____

Facility ID: 273824 Type: WELL API Number: 077-08815 Status: IJ Insp. Status: TA

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 0 Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: WMFK
 TC: Pressure or inches of Hg 0 Previous Test Pressure _____ Last MIT: 09/05/2014
 Brhd: Pressure or inches of Hg 0 Previous Test Pressure _____ AnnMTReq: _____

Comment: Routine UIC Inspection. Well temporarily abandoned.
 Corrective Action: _____ Date: _____

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____
 Corrective Action: _____ Date: _____

Facility ID: 296116 Type: WELL API Number: 077-09652 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift
 Corrective Action: _____ Date: _____

Facility ID: 296118 Type: WELL API Number: 077-09654 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

| | | | |
|---|------------------------------|-------|--|
| Corrective Action: | | Date: | |
| Facility ID: <u>296119</u> Type: <u>WELL</u> API Number: <u>077-09655</u> Status: <u>PR</u> Insp. Status: <u>PR</u> | | | |
| Producing Well | | | |
| Comment: | Plunger lift | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>296120</u> Type: <u>WELL</u> API Number: <u>077-09650</u> Status: <u>PR</u> Insp. Status: <u>PR</u> | | | |
| Producing Well | | | |
| Comment: | Plunger lift | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>296121</u> Type: <u>WELL</u> API Number: <u>077-09649</u> Status: <u>PR</u> Insp. Status: <u>PR</u> | | | |
| Producing Well | | | |
| Comment: | Plunger lift | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>296124</u> Type: <u>WELL</u> API Number: <u>077-09646</u> Status: <u>PR</u> Insp. Status: <u>PR</u> | | | |
| Producing Well | | | |
| Comment: | Plunger lift | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>297881</u> Type: <u>WELL</u> API Number: <u>077-09709</u> Status: <u>PR</u> Insp. Status: <u>PR</u> | | | |
| Producing Well | | | |
| Comment: | Plunger lift | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|-----------------|--------------------------|---------|
| Berms | Pass | Gravel | Pass | Self Inspection | Pass | |
| Gravel | Pass | Ditches | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT