

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/08/2017

Submitted Date:

06/09/2017

Document Number:

680401657**FIELD INSPECTION FORM**

Loc ID 334514 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 760 HORIZON DRIVE #101City: GRAND JUNCTION State: CO Zip: 81506**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Bankert, Wayne	970-683-5419	cogccnotifications@laramie-energy.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221788	WELL	IJ	02/01/2017	DSPW	077-08390	ZIEGAL 7-1	SI
280315	WELL	PR	04/15/2006	GW	077-08954	MY WAY RANCH 7-7	PR
280316	WELL	PR	09/29/2005	GW	077-08953	MY WAY RANCH 7-2	PR
280319	WELL	PR	12/29/2005	GW	077-08952	MY WAY RANCH 7-1A	PR

General Comment:

Routine UIC Inspection.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	
Type	Main		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Injection well in housing		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 3		corrective date
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Pump in housing		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		39.205891,-107.917436
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	300 BBLS	STEEL AST		39.205933,-107.917052
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 221788 Type: WELL API Number: 077-08390 Status: IJ Insp. Status: SI**Underground Injection Control**

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg -5 Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: WMFK

TC: Pressure or inches of Hg 13 Previous Test Pressure _____ Last MIT: 07/30/2013

Brhd: Pressure or inches of Hg 22 Previous Test Pressure _____ AnnMTReq: _____

Comment: Routine UIC Inspection. Well shut in.

Corrective Action: _____ Date: _____

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 280315 Type: WELL API Number: 077-08954 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action: _____ Date: _____

Facility ID: 280316 Type: WELL API Number: 077-08953 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action: _____ Date: _____

Facility ID: 280319 Type: WELL API Number: 077-08952 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	Self Inspection	Pass	
Gravel	Pass	Ditches	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT