

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2017

Submitted Date:

06/09/2017

Document Number:

674005353**FIELD INSPECTION FORM**

Loc ID 418319 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418317	WELL	PR	12/17/2010	OW	123-31898	NCLP USX AA 05-16	PA

**General Comment:**

Inspected Facilities									
Facility ID:	418317	Type:	WELL	API Number:	123-31898	Status:	PR	Insp. Status:	PA

COGCC Comments		
Comment	User	Date
Form 6 in COGCC data base, document number: 401099882 Well not observed.	carlilec	06/09/2017